



Customer Technical Bulletin



Hologic Validated Microsoft Security Updates for the Genius™ Digital Diagnostics System Worldwide Distribution

Purpose:

The purpose of this Customer Technical Bulletin (CTB) is to provide information on the Hologic validated security updates for Microsoft products incorporated in the Genius™ Digital Diagnostics system.

Scope:

This CTB is effective upon receipt and is intended for Genius™ Digital Diagnostics System site administrators, operators, and laboratory supervisors.

This CTB is provided upon customer request.

What is Affected:

Hologic has validated the following OS, App, and Anti-virus updates for installation on the Genius™ Digital Diagnostics System.

Genius™ Image Management Server:

Windows Server 2016 OS - KB4589210, KB5032391, KB5034119, KB5034767, KB5035855, KB5036899, KB5037763, KB5039214, KB5040434, KB5041773, KB5043051, KB5044293, KB5046612, KB5048671, KB5049993, KB5052006, KB5053594, KB5055521, KB5061010, KB5062560, KB5063871

Windows Server 2019 OS - KB5031222, KB5032337, KB5034127, KB5034768, KB5035849, KB5036896, KB5037765, KB5039217, KB5040430, KB5041578, KB5043050, KB5044277, KB5046615, KB5048661, KB505008, KB5052000, KB5053596, KB5055519, KB5060531, KB5062557, KB5063877

Windows Server 2022 OS - KB5031221, KB5032336, KB5034129, KB5034770, KB5035857, KB5036909, KB5037782, KB5039227, KB5040437, KB5041160, KB5042881, KB5044281, KB5046616, KB5048654, KB5049983, KB5051979, KB5053603, KB5055526, KB5060526, KB5062572, KB5063880

Genius™ Review Station:

Windows 10 OS - KB5031904, KB5032189, KB5034122, KB5034763, KB5035845, KB5036892, KB5037768, KB5039211, KB5040427, KB5041580, KB5043064, KB5044273, KB5046613, KB5048652, KB5049981, KB5051974, KB5053606, KB5055518, KB5060533, KB5062554, KB5063709

Windows 11 OS - KB5031455, KB5032190, KB5034123, KB5034765, KB5035853, KB5036909, KB5037771, KB5039212, KB5040442, KB5041585, KB5043076, KB5044285, KB5048685, KB5050021, KB5051979, KB5053602, KB5055528, KB5060999, KB5062572, KB5063775

Google Chrome: 119.0.6045.124, 119.0.6045.200, 120.0.6099.217, 121.0.6167.185, 122.0.6261.112, 123.0.6312.123, 124.0.6367.202, 126.0.6478.62, 126.0.6478.127, 127.0.6533.101, 128.0.6613.138, 129.0.6668.101, 131.0.6778.70, 131.0.6778.140, 132.0.6834.84, 133.0.6943.99, 134.0.6998.89, 135.0.7049.85, 138.0.7204.50, 138.0.7204.169, 139.0.7258.128

Anti-Virus:**MalwareBytes (Server):**

Agent version:2.0.0.261

Endpoint Protection:2.0.0.40

Asset Manager:2.0.0.30

MalwareBytes (Workstation):

Agent version:2.0.0.261

Brute Force Protection:2.0.0.69

Endpoint Protection:2.0.0.40

Endpoint Protection protection update:1.0.101971

Protection service version:4.6.34.393

Component package version:1.0.2557

Asset Manager:2.0.0.30

ESET (Server):

Version V12.0.12005.0

Detection Engine: 31694

ESET (Workstation):

Version V12.0.2058.0

Detection Engine: 31694

Defender

1.435.183.0

What is Required:

Genius Digital Diagnostic System components should be updated with the current version of the OS, App, and Anti-virus updates.

If there are any questions or concerns regarding this communication, please contact your local Hologic support representative. Alternatively, country-specific telephone contact information for Technical Support can be found at www.hologic.com/support.

END OF DOCUMENT