



Date: 01/31/2022

Author: Software Engineering

System: Apex

Subsystem: Microsoft Win Pro Embedded 10 LTSB 2016

Subject: Microsoft Win Pro Embedded 10 LTSB 2016 Patch release January 2022

To release the list of validated Microsoft critical patches on the Apex Win Pro Embedded 10 LTSB 2016 systems.

Note 1: If you are using the following versions of APEX, if you are required to update to the latest Hologic validated Windows updates, you must ensure your system(s) have been patched with the ‘Sentinel Run-Time 7.80.0.0’ which can be located in the Windows Control Panel ‘Program and Features’. If needed you can install the patch by ordering ‘APEX Service Dongle Patch Release’ (ASY-12610). Please contact Hologic Support if you have any questions.

| System Type | Software Versions |
|-------------|-------------------|
| Horizon | APEX v5.6.0.7 |
| Workstation | APEX v5.6.0.7 |

List of patches/KB’s validated for January 2022:

KB5009557 KB5008873 KB4589208

List of all patches/KB’s validated on the Apex System:

KB890830 KB5004238 KB4601318
 KB5009557 KB5003638 KB4598243
 KB5008873 KB5003197 KB4593226
 KB5008207 KB5001402 KB4589210
 KB5007192 KB5001347 KB4589208
 KB5006669 KB5001078 KB4586830
 KB5005698 KB5000803 KB4583462
 KB5005573 KB5000645 KB4580346
 KB5005043 KB4601392 KB4580325

| | |
|-----------|-----------|
| KB4577586 | KB4132216 |
| KB4577015 | KB4052908 |
| KB4576750 | KB4022619 |
| KB4571694 | KB4018073 |
| KB4565912 | KB2565063 |
| KB4565511 | KB2467173 |
| KB4562561 | |
| KB4561616 | |
| KB4561600 | |
| KB4556813 | |
| KB4550994 | |
| KB4550929 | |
| KB4540723 | |
| KB4540670 | |
| KB4537764 | |
| KB4537759 | |
| KB4535680 | |
| KB4535288 | |
| KB4534271 | |
| KB4530689 | |
| KB4520724 | |
| KB4516115 | |
| KB4516044 | |
| KB4512574 | |
| KB4505422 | |
| KB4503537 | |
| KB4503308 | |
| KB4503267 | |
| KB4498947 | |
| KB4494175 | |
| KB4346087 | |