

Date: 12/20/2021
Author: Software Engineering
System: Apex
Subsystem: Microsoft Win Pro Embedded 10 LTSB 2016
Subject: Microsoft Win Pro Embedded 10 LTSB 2016 Patch release November 2021

To release the list of validated Microsoft critical patches on the Apex Win Pro Embedded 10 LTSB 2016 systems.

Note 1: If you are using the following versions of APEX, if you are required to update to the latest Hologic validated Windows updates, you must ensure your system(s) have been patched with the "Sentinel Run-Time 7.80.0.0" which can be located in the Windows Control Panel "Program and Features". If needed you can install the patch by ordering "APEX Service Dongle Patch Release" (ASY-12610). Please contact Hologic Support if you have any guestions.

| System Type | Software Versions |
|----------------|----------------------|
| Horizon | APEX v5.6.0.7 |
| Workstation | APEX v5.6.0.7 |

List of patches/KB's validated for November 2021:

KB4583462 KB4018073

List of all patches/KB's validated on the Apex System:

| KB890830 | KB5003197 | KB4598243 |
|-----------|-----------|-----------|
| KB5007192 | KB5001402 | KB4593226 |
| KB5006669 | KB5001347 | KB4589210 |
| KB5005698 | KB5001078 | KB4586830 |
| KB5005573 | KB5000803 | KB4583462 |
| KB5005043 | KB5000645 | KB4580346 |
| KB5004238 | KB4601392 | KB4580325 |
| KB5003638 | KB4601318 | KB4577586 |

| KB4577015 | KB4052908 |
|-----------|-----------|
| KB4576750 | KB4022619 |
| KB4571694 | KB4018073 |
| KB4565912 | KB2565063 |
| KB4565511 | KB2467173 |
| KB4562561 | |
| KB4561616 | |
| KB4561600 | |
| KB4556813 | |
| KB4550994 | |
| KB4550929 | |
| KB4540723 | |
| KB4540670 | |
| KB4537764 | |
| KB4537759 | |
| KB4535680 | |
| KB4535288 | |
| KB4534271 | |
| KB4530689 | |
| KB4520724 | |
| KB4516115 | |
| KB4516044 | |
| KB4512574 | |
| KB4505422 | |
| KB4503537 | |
| KB4503308 | |
| KB4503267 | |
| KB4498947 | |
| KB4494175 | |
| KB4346087 | |
| KB4132216 | |