



**Date:** July 13, 2022

**Author:** Software Engineering

**System:** Apex

**Subsystem:** Microsoft Win Pro Embedded 10 LTSP 2016

**Subject:** Microsoft Win Pro Embedded 10 LTSP 2016 Patch release June 2022

---

**Purpose:**

To release the list of validated Microsoft critical patches on the Apex Win Pro Embedded 10 LTSP 2016 systems.

Note 1: If you are using the following versions of APEX, if you are required to update to the latest Hologic validated Windows updates, you must ensure your system(s) have been patched with the “Sentinel Run-Time 7.80.0.0” which can be located in the Windows Control Panel “Program and Features”. If needed you can install the patch by ordering “APEX Service Dongle Patch Release” (ASY-12610). Please contact Hologic Support if you have any questions.

System Type	Software Versions
Horizon	APEX v5.6.0.7
Workstation	APEX v5.6.0.7

**List of patches/KB’s validated for June 2022:**

KB5014702

**List of all patches/KB’s validated on the Apex System:**

KB890830	KB5008207	KB5001347
KB5014702	KB5007192	KB5001078
KB5014026	KB5006669	KB5000803
KB5013952	KB5005698	KB5000685
KB5012596	KB5005573	KB5000645
KB5011570	KB5005043	KB4601392
KB5011495	KB5004238	KB4601318
KB5010359	KB5003638	KB4598243
KB5009557	KB5003197	KB4593226
KB5008873	KB5001402	KB4589210

KB4589208	KB4503308
KB4586830	KB4503267
KB4583462	KB4498947
KB4580346	KB4494175
KB4580325	KB4346087
KB4577586	KB4132216
KB4577015	KB4052908
KB4576750	KB4022619
KB4571694	KB4018073
KB4565912	KB2565063
KB4565511	KB2467173
KB4562561	
KB4561616	
KB4561600	
KB4556813	
KB4550994	
KB4550929	
KB4540723	
KB4540670	
KB4537764	
KB4537759	
KB4535680	
KB4535288	
KB4534271	
KB4530689	
KB4520724	
KB4516115	
KB4516044	
KB4512574	
KB4505422	
KB4503537	