

Date: 11/02/2021

Author: Software Engineering

System: Apex

Subsystem: Microsoft Win Pro Embedded 10 LTSB 2016

Subject: Microsoft Win Pro Embedded 10 LTSB 2016 Patch release October

2021

To release the list of validated Microsoft critical patches on the Apex Win Pro Embedded 10 LTSB 2016 systems.

Note 1: If you are using the following versions of APEX, if you are required to update to the latest Hologic validated Windows updates, you must ensure your system(s) have been patched with the "Sentinel Run-Time 7.80.0.0" which can be located in the Windows Control Panel "Program and Features". If needed you can install the patch by ordering "APEX Service Dongle Patch Release" (ASY-12610). Please contact Hologic Support if you have any questions.

System Type	Software Versions
Horizon	APEX v5.6.0.7
Workstation	APEX v5.6.0.7

List of patches/KB's validated for October 2021:

KB5006669	KB5000645	KB4052908
INDUGGGGG	INDUUUUTU	INDTUCEUU

List of all patches/KB's validated on the Apex System:

KB890830	KB5001347	KB4586830
KB5006669	KB5001078	KB4583462
KB5005698	KB5000803	KB4580346
KB5005573	KB5000645	KB4580325
KB5005043	KB4601392	KB4577586
KB5004238	KB4601318	KB4577015
KB5003638	KB4598243	KB4576750
KB5003197	KB4593226	KB4571694
KB5001402	KB4589210	KB4565912

KB4565511	KB2467173
KB4562561	
KB4561616	
KB4561600	
KB4556813	
KB4550994	
KB4550929	
KB4540723	
KB4540670	
KB4537764	
KB4537759	
KB4535680	
KB4535288	
KB4534271	
KB4530689	
KB4520724	
KB4516115	
KB4516044	
KB4512574	
KB4505422	
KB4503537	
KB4503308	
KB4503267	
KB4498947	
KB4494175	
KB4346087	
KB4132216	
KB4052908	
KB4022619	
KB4018073	

KB2565063