



**Date:** November 9, 2022

**Author:** Software Engineering

**System:** Apex

**Subsystem:** Microsoft Win Pro Embedded 10 LTSP 2016

**Subject:** Microsoft Win Pro Embedded 10 LTSP 2016 Patch release October 2022

---

**Purpose:**

To release the list of validated Microsoft critical patches on the Apex Win Pro Embedded 10 LTSP 2016 systems.

Note 1: If you are using the following versions of APEX, if you are required to update to the latest Hologic validated Windows updates, you must ensure your system(s) have been patched with the "Sentinel Run-Time 7.80.0.0" which can be located in the Windows Control Panel "Program and Features". If needed you can install the patch by ordering "APEX Service Dongle Patch Release" (ASY-12610). Please contact Hologic Support if you have any questions.

System Type	Software Versions
Horizon	APEX v5.6.0.7
Workstation	APEX v5.6.0.7

**List of patches/KB's validated for October 2022:**

KB5018411

**List of all patches/KB's validated on the Apex System:**

KB890830	KB5014026	KB5007192
KB5018411	KB5013952	KB5006669
KB5017396	KB5012596	KB5005698
KB5017305	KB5012170	KB5005573
KB5017095	KB5011570	KB5005043
KB5016622	KB5011495	KB5004238
KB5016058	KB5010359	KB5003638
KB5015808	KB5009557	KB5003197
KB5014702	KB5008873	KB5001402
KB5014164	KB5008207	KB5001347

KB5001078	KB4535288
KB5000803	KB4534271
KB5000685	KB4530689
KB5000645	KB4520724
KB4601392	KB4516115
KB4601318	KB4516044
KB4598243	KB4512574
KB4593226	KB4505422
KB4589210	KB4503537
KB4589208	KB4503308
KB4586830	KB4503267
KB4583462	KB4498947
KB4580346	KB4494175
KB4580325	KB4346087
KB4577586	KB4132216
KB4577015	KB4052908
KB4576750	KB4022619
KB4571694	KB4018073
KB4565912	KB2565063
KB4565511	KB2467173
KB4562561	
KB4561616	
KB4561600	
KB4556813	
KB4550994	
KB4550929	
KB4540723	
KB4540670	
KB4537764	
KB4537759	
KB4535680	