



**Date:** 10/07/2021

**Author:** Software Engineering

**System:** Apex

**Subsystem:** Microsoft Win Pro Embedded 10 LTSP 2016

**Subject:** Microsoft Win Pro Embedded 10 LTSP 2016 Patch release September 2021

**Purpose:**

To release the list of validated Microsoft critical patches on the Apex Win Pro Embedded 10 LTSP 2016 systems.

Note 1: If you are using the following versions of APEX, if you are required to update to the latest Hologic validated Windows updates, you must ensure your system(s) have been patched with the "Sentinel Run-Time 7.80.0.0" which can be located in the Windows Control Panel "Program and Features". If needed you can install the patch by ordering "APEX Service Dongle Patch Release" (ASY-12610). Please contact Hologic Support if you have any questions.

System Type	Software Versions
Horizon	APEX v5.6.0.7
Workstation	APEX v5.6.0.7

**List of patches/KB's validated for September 2021:**

KB5005698                      KB5005573

**List of all patches/KB's validated on the Apex System:**

KB890830	KB5001078	KB4580346
KB5005698	KB5000803	KB4580325
KB5005573	KB4601392	KB4577586
KB5005043	KB4601318	KB4577015
KB5004238	KB4598243	KB4576750
KB5003638	KB4593226	KB4571694
KB5003197	KB4589210	KB4565912
KB5001402	KB4586830	KB4565511
KB5001347	KB4583462	KB4562561

KB4561616

KB4561600

KB4556813

KB4550994

KB4550929

KB4540723

KB4540670

KB4537764

KB4537759

KB4535680

KB4535288

KB4534271

KB4530689

KB4520724

KB4516115

KB4516044

KB4512574

KB4505422

KB4503537

KB4503308

KB4503267

KB4498947

KB4494175

KB4346087

KB4132216

KB4022619

KB4018073

KB2565063

KB2467173